



Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 1
Date: 03/30/95 Time: 0910
Photographer: John Noyes
Description: Large lagoon with aerators, water, and rocky shore.
Onsite storage building in background. View is to
the north.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 2
Date: 03/30/95 Time: 0910
Photographer: John Noyes
Description: Large lagoon with aerators, water, and rocky shore.
Onsite storage building in background. View is to
the north.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 3
Date: 03/30/95 Time: 0913
Photographer: John Noyes
Description: Large lagoon with aerators, water, and rocky shore.
Onsite storage building in background. View is to
the northeast.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 4
Date: 03/30/95 Time: 0913
Photographer: John Noyes
Description: Large lagoon with aerators, water, and rocky shore.
Onsite storage building in background. View is to
the northeast.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 5
Date: 03/30/95 Time: 0915
Photographer: John Noyes
Description: The first small lagoon. Note the standing water
due to recent rains. Weir in background leads to a
sealed underground drainage pipe. View is to
the west.



Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 6
Date: 03/30/95 Time: 0915
Photographer: John Noyes
Description: The first small lagoon. Note the standing water due to recent rains. Weir in background leads to a sealed underground drainage pipe. View is to the west.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 7
Date: 03/30/95 Time: 0918
Photographer: John Noyes
Description: The second small lagoon (south of the first small lagoon). No standing water. Weir in background leads to a sealed underground drainage pipe. View is to the west.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 8
Date: 03/30/95 Time: 0918
Photographer: John Noyes
Description: The second small lagoon (south of the first small lagoon). No standing water. Weir in background leads to a sealed underground drainage pipe. View is to the west.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 9
Date: 03/30/95 Time: 0925
Photographer: John Noyes
Description: Gate and fence enclosing surface lagoons. Note berms inside fence surrounding each lagoon. View is to the west.

Site: Diamond International Corporation
Proj#: 71380.114 - ILD 980 683 197
Roll: 2 Photo #: 10
Date: 03/30/95 Time: 0925
Photographer: John Noyes
Description: Gate and fence enclosing surface lagoons. Note berms inside fence surrounding each lagoon. View is to the west.